



Dynamic Control - Test carried out on 300m



MECHANICAL PARTS (lift view)

Underbody	Condition	Usury
Structure	✓	
Transmission	✓	
Steering	✓	
Bearing	✓	Front Rear
Suspension/ ball / front arm / rear arm	✓	
Evidence of serious accident	No	
Engine	Condition	Detail
Start vehicle	✓	
Exhaust system	✓	
Braking System	Avant	Arrière
Brake pads set	✓	✓
Brake disc	✓	✓
TYRE CONDITION	Usury*	Mesure en mm
Front Axle	Hors d'usage	1
Rear Axle	Acceptable	1

MECHANICAL PARTS (TOP VIEW)

	Condition
Fuel	✓
Oil	✓
Coolant fluid	✓
Steering fluid	A
Brakes fluid	✓
Serpentine Belt	✓
Uper crossmember	✓
Control liquid leak	✓

DASHBOARD

(voyants constatés lors de l'essai)

Operation indicators	Condition
Lighting dashboard	✓
Led engine	✓
ABS/Braking	✓
Airbag	✓
Pollution	✓
Oil	✓
Injection	✓

EQUIPMENT Test

Equipment Test	Condition
Navi test	✓
Audio test	✓
Presence CD/DVD/memory card	✓
Airconditioning test (compressor)	✓
Electric windows test	✓
Central locking test	✓
sunroof test, Convertible test	A
Dump / Trail / Tail gate lift	A
Presence anti-theft Lock nut	✓

MAINTENANCE DOCUMENTS

Maintenance Documents	Condition
Last maintenance (date)	00/0000
Last mileage maintenance	
Others documents	None
Handbook	✓

COMMENTS :

The technical inspection is a visual and a dynamic diagnostic performed without disassembly, thus we can't guarantee wear powertrains

*Wear on the tread controlled
 A = Not available / N = Not visible / NC = Not controllable